

TABLE OF CONTENTS

EXECUTIVE SUMMARY

SECTION 1 – BACKGROUND.....6

SECTION 2 – INTRODUCTION.....9

SECTION 3 – MONITORING AND EVALUATION: METHODS,
OVERALL RESULTS AND DISCUSSION.....11

- 3.1 Channel Stability and Morphology.....11
- 3.2 Riparian Vegetation.....17
- 3.3 Benthic Macroinvertebrates.....22
- 3.4 Suspended Sediment.....24

SECTION 4 – MONITORING AND EVALUATION: SITE SPECIFIC
RESULTS AND DISCUSSION.....29

- 4.1 Warne.....29
- 4.2 Bell.....31
- 4.3 Hyatt.....33
- 4.4 Oland.....35
- 4.5 Mason/Stalcup.....36
- 4.6 Sheppard.....38
- 4.7 J. Carringer/Mitchell.....40
- 4.8 Campbell (Folk School).....42
- 4.9 Long Branch.....44
- 4.10 Greasy Creek.....45

SECTION 5 – CONCLUSION.....49

SECTION 6 – NEXT STEPS.....51

LITERATURE CITED

LIST OF FIGURES

Figure 1	Topographic vicinity map of the Brasstown Creek watershed.....	7
Figure 2	Map of HRWC restoration sites within the North Carolina portion of the Brasstown Creek watershed.....	10
Figure 3	Air temperatures in the riparian buffer and an adjacent field at the Hyatt project site along Brasstown Creek during one week in August 2007.....	20
Figure 4	Water temperatures during the warmest week of 2007 upstream and downstream of the Sheppard project site along Little Brasstown Creek.....	21
Figure 5	Total Suspended Solids concentrations upstream and downstream of the restored reach during eight high-flow events at the Mason/Stalcup project site.....	26
Figure 6	Total Suspended Solids concentrations upstream and downstream of the restored reach during eight high-flow events at the Carringer/Mitchell project site.....	26

LIST OF TABLES

Table 1	Average ratings of monitored structures by year and project site.....	13
Table 2	Summary of benthic macroinvertebrate data by year and by project location.....	23